# Montana Board of Oil and Gas Conservation Environmental Assessment

Operator: Marathon Oil Company.
Well Name/Number: Haral Hoff 41-30H
Location: NE ND Section 30 T31N R59E
County: Sheridan, MT; Field (or Wildcat) Wildcat
Air Quality
(possible concerns)
Long drilling time: No, 25-35 days drilling time.
Unusually deep drilling (high horsepower rig): Triple derrick drilling rig, to drill to
19,691'MD/9,943'TVD single lateral Bakken Formation test well
Possible H2S gas production: Yes, slight chance of H2S gas, Mississippian Formations.
In/near Class I air quality area: No Class I air quality area.
Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required under
<u>75-2-211.</u>
Mitigation:
X Air quality permit (AQB review)
Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
Other:
Comments: Drill a 19,691'MD/9,943'TVD single lateral Bakken Formation test well.
If no gas gathering system exists nearby sweet gas and/or H2S gas can be flared under Board_
Rule 36.22.1220. No concerns.
<b>TY</b> 4 O 194

## Water Quality

(possible concerns)

Salt/oil based mud: Yes to intermediate casing string hole will be drilled with oil based invert drilling fluids. Horizontal lateral will be drilled with brine water. Surface casing hole will be drilled with freshwater and freshwater mud system.

High water table: No high water table anticipated, in the area of review.

Surface drainage leads to live water: No, closest drainage is an unnamed ephemeral tributary to Brush Mountain Creek, about 1/4 of a mile to the south and 3/8 of a mile to the west from this location.

Water well contamination: None, closest water wells are about 3/8 of a mile to the west northwest and about 7/8 of a mile to the west southwest from this location. Surface hole will be drilled with freshwater to 1900'. Surface casing will be run and cemented to surface.

Porous/permeable soils: No, silty sandy clay soils.

Class I stream drainage: No, Class I stream drainages.

Mitigation:

- X Lined reserve pit
- X Adequate surface casing
- \_\_ Berms/dykes, re-routed drainage
- X Closed mud system
- X\_ Off-site disposal of solids/liquids (in approved facility)
- X Other: <u>Semi closed loop mud system to be used</u>. Oil based invert drilling fluids will be recycled. Cuttings will be mixed with fly ash and buried in the lined cuttings pit on the

wellsite.

Comments: 1900' of surface casing will be necessary to cover the base of the Fox Hills aquifer.

### Soils/Vegetation/Land Use

/ •1 1	\ \
(nossible	concerns)
( possible	COMCOMIS

Steam crossings: None anticipated.

High erosion potential: No high erosion potential, location requires a small cut, up to 8.7' and a moderate fill, up to 11.1', .required.

Loss of soil productivity: <u>Slight.</u>

Unusually large wellsite: No, a very large well site 400'X500', single well location pad. Damage to improvements: No, location to be restored after drilling, if nonproductive. If productive unused portion of the drilling pad will be reclaimed.

Conflict with existing land use/values: <u>Slight</u>, surface use is cultivated land.

3 4	r•	•	. •
1\/	11	Oa.	tion
TAT	uι.	ıza	uon

Avoid improvements (t	topographic tolerance)
-----------------------	------------------------

\_\_ Exception location requested

X Stockpile topsoil

\_\_ Stream Crossing Permit (other agency review)

X Reclaim unused part of wellsite if productive

\_\_ Special construction methods to enhance reclamation

\_\_ Other \_\_\_\_\_

Comments: Access will be over existing county gravel road, Brush Mountain Road and existing lease road into the Raymond Sveet 31-29H location. Estimated amount of new road to be constructed is about 1 mile into this location from the Raymond Sveet 31-29H location.

Cuttings will be mixed with fly ash and dumped in the lined cuttings pit. Cuttings pit will be backfilled when drilling is completed. Oil based invert drilling fluids will be recycled or hauled to a Class II disposal.

#### **Health Hazards/Noise**

(possible concerns)

Proximity to public facilities/residences: <u>Closest residences are about 7/8 of a mile to the west northwest, about 1 1/8 of a mile to the northwest and about 1.25 miles to the northwest from this location.</u> The town of Medicine Lake, Montana lies about 20 miles to the west northwest and <u>Dagmar</u>, Montana lies 12.5 miles to the northwest from this location.

Possibility of H2S: \_Slight chance of H2S, Mississippian Formations.

Size of rig/length of drilling time: <u>Triple drilling rig 25 to 35 days drilling time</u>.

# Mitigation:

X Proper BOP equipme	n	t
----------------------	---	---

- \_\_ Topographic sound barriers
- \_\_ H2S contingency and/or evacuation plan
- \_\_ Special equipment/procedures requirements

Other:						

Comments: <u>Adequate surface casing cemented to surface with working BOP stack should mitigate any problems.</u>

#### Wildlife/recreation

whatte/recreation
(possible concerns)
Proximity to sensitive wildlife areas (DFWP identified): Medicine Lake National Wildlife
Refuge is about 10.5 miles to the northwest from this location.
Proximity to recreation sites: Medicine Lake National Wildlife Refuge is about 10.5 miles to
the northwest from this location.
Creation of new access to wildlife habitat: No
Conflict with game range/refuge management: No
Threatened or endangered Species: <u>Threatened or endangered species listed on the Region 6</u>
USFW website are the Piping Plover and Whooping Crane. Candidate species is the Sprague's
Pipit. NH Tracker website lists two (2) species of concern as follows: Burrowing Owl, and
Whooping Crane
Mitigation:
Avoidance (topographic tolerance/exception)
Other agency review (DFWP, federal agencies, DSL)
Screening/fencing of pits, drillsite
Other:
Comments: Private surface cultivated land. There may be species of concern that maybe
impacted by this wellsite. We ask the operator to consult with the surface owner as to what he
would like done, if a species of concern is discovered at this location. The Board of Oil & Gas
has no jurisdiction over private surface lands.
Historical/Cultural/Dalcantalogical
Historical/Cultural/Paleontological (possible concerns)
Proximity to known sites: None identified.
Mitigation
avoidance (topographic tolerance, location exception)
avoidance (topographic tolerance, location exception) other agency review (SHPO, DSL, federal agencies)
Other:
Comments: Private surface cultivated land. There may be possible
historical/cultural/paleontological sites that maybe impacted by this wellsite. We ask the
operator to consult with the surface owner as to his desires to preserve these sites or not, if they
are found during construction of the wellsite. The Board of Oil & Gas has no jurisdiction over
private surface lands.
private surface lands.
Social/Economic
(possible concerns)
Substantial effect on tax base
Create demand for new governmental services
Population increase or relocation
Comments: Wildcat well. No concerns

Remarks or Special Concerns for this site

This will be an 19,691'MD/9,943'TVD single lateral Bakken Formation test well.

## **Summary: Evaluation of Impacts and Cumulative effects**

No long term impacts expected from the drilling of this well. Some short term impacts will occur, but will be mitigated in time.

I conclude that the approval of the subject Notice of Intent to Drill (does/<u>does not</u>) constitute a major action of state government significantly affecting the quality of the human environment, and (does/<u>does not</u>) require the preparation of an environmental impact statement.

Prepared by (BOGC): /s/Steven Sasaki
(title:) Chief Field Inspector
Date: July 24, 2012
Other Persons Contacted:
Montana Bureau of Mines and Geology, GWIC website
(Name and Agency)
Water wells in Sheridan County
(subject discussed)
July 24, 2012
(date)
US Fish and Wildlife, Region 6 website
(Name and Agency)
ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA
COUNTIES, Sheridan County, Montana
(subject discussed)
July 24, 2012
<del></del>
Montana Natural Heritage Program Website
(Name and Agency)
Heritage State Rank= S1, S2, S3, Location T31N R59E
(subject discussed)
July 24, 2012
(date)
If location was inspected before permit approval:
Inspection date:
<u>=</u>
Inspector:
Others present during inspection: